
Appendix F

Windows 95 Minimum ROM-Revisions

and

Support Software CD Information

Windows 95 Minimum ROM-Revisions

Minimum System ROM-Revisions for Windows 95*	ROM Revision Date	Spare Part
Portables		
Contura 486 Family	101293	181088-001 146330-001
Contura Aero	071995	181088-001
Contura 400/410	071895	181088-001
Contura 420/430	082195	181088-001
LTE Elite	071995	181088-001
LTE 486 Lite	032394	181088-001
LTE 5000	021595	182358-001
Desktop/Mini Tower		
Deskpro 4100	072695	148218-001
Deskpro 575	072695	148218-001
Deskpro 590	072695	148218-001
Deskpro 5100	072695	148218-001
Deskpro XE 586 Family	103194	148218-001
Deskpro XE 486 Family	110294	148218-001
Deskpro XL	062895	148218-001
Presario 500 Family	051295	177185-001
Presario 700/900 Family (486C04)	051195	171154-001
Presario 700/900 Family (486C07)	062795	200930-001
Presario 900 Pentium Family (586G)	051295	148218-001
Presario 7100 486 Family	080495	188821-001
Presario 7100 586 Family	081095	188821-001
ProLinea 450	072695	148218-001
ProLinea 466	072695	148218-001
ProLinea 4100	072695	148218-001
ProLinea 575	072695	148218-001
ProLinea 590	072695	148218-001
ProLinea 5100	072695	148218-001
ProLinea (Enhanced) Desktop Family	073194	164562-001
ProLinea MT	050294	181044-001

* All units with a system ROM date newer than 090195 are Win95 compliant.

Compaq Windows 95 Upgrade Kits/Manual	Spare Part ²
Windows 95 User's Guide (Introducing Microsoft Windows 95)	182793-xx1
Compaq Portables Windows 95 Supplemental Kit ¹	182900-xx1
Compaq Presario 500/700/900 Windows 95 Supplemental Kit ³	182796-xx1
Compaq Commercial Windows 95 Supplemental Kit	182795-xx1
Compaq Presario 7100 Windows 95 Supplemental Kit	182889-xx1
Compaq Presario 5500/9500 Windows 95 Supplemental Kit	182794-xx1
Compaq LTE 5000 Windows 95 Supplemental Diskette Kit	182886-xx1

¹ Not all languages apply to Supplemental kits. Please see Service Advisories for appropriate language support

² Refer to "Language Extensions" table (next page) for -xx1 specifics

³ Presario 500/700/900 machines need to have at least MediaPilot 1.5 for their telephony software to operate properly. Please see Service Advisory 831 for upgrade information.