

## iPAQ BlackBerry H1100

The Compaq iPAQ BlackBerry H1100 is covered by a One-Year Limited North America Warranty, which includes parts and labor. The H1100 is covered by an Advance Exchange Warranty. Should a H1100 require repair during the warranty period, call Compaq Technical Support. A Technical Support Specialist will help diagnose the problem. If needed, Compaq will ship the customer a replacement part. Carry-In Warranty is not available in North America.

Configuration Code	Description	Spare Part*
FS35	H1100, 5MB, US Base Configuration	213702-001
FS35	H1100, 5MB, Canadian Base Configuration	213702-002
FS35	H1100, 5 MB, Email, US Base Configuration	192705-001

\*The H1100 is spared as a whole unit and contains no serviceable parts. The unit contains a non-removable LiIon battery.

Miscellaneous	Spare Part
AC Adapter, DIR CONN	216337-001
AC Adapter, US	213705-001
Belt Clip	213704-001
CDROM, Desktop	194576-001
CDROM, Enterprise Server	194579-001
Cradle	213703-001
User Guide, H1100	194578-001
User Guide, Enterprise Server	194580-001

# iPAQ BlackBerry H1100

## Memory Upgrade Chart

There are no internal memory upgrades for the iPAQ BlackBerry H1100.