

iPAQ BlackBerry W1000

The Compaq iPAQ BlackBerry W1000 is covered by a One-Year Limited North America Warranty, which includes parts and labor. The W1000 is covered by an Advance Exchange Warranty. Should a W1000 require repair during the warranty period, call Compaq Technical Support. A Technical Support Specialist will help diagnose the problem. If needed, Compaq will ship the customer a replacement part. Carry-In Warranty is not available in North America.

Configuration Code	Description	Spare Part*
FS31	W1000, 4MB, Email, US Base Configuration	212995-001
FS33	W1000, 4MB, US Base Configuration	194573-001
FS33	W1000, 4MB, Canadian Base Configuration	194573-002

*The W1000 is spared as a whole unit and contains no serviceable part. The spare kit contains a size AA battery.

Miscellaneous	Spare Part
Battery Door	194574-001
Belt Clip	194572-001
CDROM, Desktop	194576-001
CDROM, Enterprise Server	194579-001
Cradle	194577-001
User Guide, W1000	194575-001
User Guide, Enterprise Server	194580-001

iPAQ BlackBerry W1000

Memory Upgrade Chart

There are no internal memory upgrades for the iPAQ BlackBerry W1000.