

# T1000/T1500

The Compaq T1000/T1500 is covered by a 3-Year Limited Worldwide Warranty, which includes parts and labor. In North America, the T1000/T1500 is covered by a Mail-In Warranty. Should a T1000/T1500 require repair during the warranty period, call Compaq Technical Support. A technical support specialist will help diagnose the problem. If needed, the customer will be directed where to mail the unit for service. Carry-In Warranty is not available in North America.

In all other geographic regions, the T1000/T1500 is covered by a 3-Year Limited Carry-In Warranty. The warranty covers parts and labor only. Since Warranty delivery differs based on geographic region, contact the local Compaq Customer Support organization for information on coverage specific to a particular region.

Configuration Code/Model	Description	Unit Spare Part
DHP1/T1000	Win CE OS	158133-001
DHP4/T1500	Linux OS	158134-001

Miscellaneous	Assembly	Spare Part
Ferrite Bead		159867-001
AC Adapter	158261-001	158135-001
AC Power Cord	121565-001	142766-001
AC Power Cord - Australia	100661-001	285811-001
AC Power Cord – Germany, France, Netherlands		285810-001
AC Power Cord – United Kingdom	100613-001	121259-001
Keyboard, Spacesaver, Opal	166516-006	269513-001
Keyboard, Spacesaver, Opal - International	166516-B36	269513-002
Keyboard, Spacesaver, Opal - Belgium	166516-186	269513-181
Keyboard, Spacesaver, Opal - Denmark	166516-086	269513-081
Keyboard, Spacesaver, Opal - France	166516-056	269513-051
Keyboard, Spacesaver, Opal – Germany	166516-046	269513-041
Keyboard, Spacesaver, Opal - Italy	166516-066	269513-061
Keyboard, Spacesaver, Opal - Netherlands	166516-336	269513-331
Keyboard, Spacesaver, Opal - Norway	166516-096	269513-091
Keyboard, Spacesaver, Opal - Spain	166516-076	269513-071
Keyboard, Spacesaver, Opal - Sweden	166516-106	269513-101
Keyboard, Spacesaver, Opal - Switzerland	166516-116	269513-111
Keyboard, Spacesaver, Opal – United Kingdom	166516-036	269513-031
Mouse, Opal	141649-006	166861-001

---

# T1000/T1500

## Memory Upgrade Chart

No memory options available.