

Contura Aero

System Boards	Assembly	Spare Part	System
4/25 System *	003209-002	197241-001 DISCONTINUED	4/25
4/33C System *	003489-001	199222-001	4/33C

* Without PCMCIA eject rails.

Memory Boards	Assembly	Spare Part	Option
4 MB Expansion	003296-002	190565-001	190532-001
8 MB Expansion	003308-001	190596-001	190597-001

Misc. Internal	Assembly	Spare Part	System
Backlight Inv, mono	003215-001	190522-001 DISCONTINUED	4/25
Display Panel, mono		190624-001 DISCONTINUED	4/25
Backlight Inv, color	003492-001	199223-001	4/33C
Display Panel, color		199232-001	4/33C
Trackball Assembly		197286-001	4/25, 4/33C
Trackball, Matte*		*	
Display Clutch	190638-001	185099-001	4/25
Display Clutch	190638-002	199336-001	4/33

* A Trackball (Matte), retainer ring, and/or trackball cleaning kit may be obtained directly by U.S. customers by calling 1-800-841-2761. In Canada, call 1-800-952-7689.

Misc. External	Spare Part	System
AC Adapter	190621-001	4/25, 4/33C
Automobile Adapter	190551-001	4/25, 4/33C
Convenience Base Unit	190568-001	4/25, 4/33C
Mobile Port Expander	197364-001	4/25, 4/33C
NiMH Extended Life Battery Pack	190626-001	4/25, 4/33C
NiMH Standard Battery Pack (w/spacer)	190697-001	4/25
Battery Spacer	197317-001	4/25, 4/33C
Trackball Cleaning Kit *	184115-001	All

* A Trackball (Matte), retainer ring, and/or trackball cleaning kit may be obtained directly by U.S. customers by calling 1-800-841-2761. In Canada, call 1-800-952-7689.

Hard Drives	Drive Type	Min ROM	Spare Part	System
84 MB	65	System	190660-001	4/25, 4/33C
170 MB	65	System	190661-001* DISCONTINUED	4/25
170 MB	65	System	199275-001	4/33C
250 MB	65	System	199233-001	4/25, 4/33C

* Currently restricted to 4/25 for FCC approval.

Contura Aero

Modems	Assembly	Spare Part	System
SpeedPaq 144/P PCMCIA	198112-001	194131-001	All
PCMCIA 14.4 Data + Fax *	149776-001	194097-001	All
PCMCIA 2400/9600 Data + Fax	149775-001	194098-001	All
SpeedPaq 192 PCMCIA Fax Modem	004234	187123-001	All
192 PCMCIA Fax Modem	004329	188512-001	All
288 PCMCIA Fax Modem	004467	189661-001	All

* Obsolete. Replaced by 187123-001. Must also order 187145-001 (modem adapter kit).

External Diskette	Spare Part	System
PCMCIA External 1.44 MB Diskette	190563-001	4/25, 4/33C


Cables	Used With	Spare Part	System
Display Cable	Mono display	197238-001 DISCONTINUED	4/25
Display Cable	Color display	199258-001	4/33C
Communication Cable	WinLink	197318-001	4/25, 4/33C
Trackball/Speaker Cable		197312-001	4/25, 4/33C

ROM Information	Spare Part
ROMPaq	181088-001

Power Supply/Battery	Spare Part
Power Supply	190521-001
Clock Battery	117099-001

Contura Aero

AERO 4/25, 4/33C MEMORY UPGRADE CHART



MAXIMUM MEMORY IS 12 MB

ADD ANY ONE OF THE FOLLOWING
MEMORY MODULES:

4 MB MEMORY MODULE
OPTION PN 190532-001

8 MB MEMORY MODULE
OPTION PN 190597-001