

Aero 1500 Palm-Size PC

The Compaq Aero 1500 is covered by a One-Year Limited Worldwide Warranty, which includes parts and labor. In North America, EMEA and Japan, the Aero 1500 is covered by a Mail-In Warranty. Should an Aero 1500 require repair during the warranty period, call Compaq Technical Support. A technical support specialist will help diagnose the problem. If needed, the customer will be directed where to mail the unit for service. Carry-In Warranty is not available in North America, Europe or Japan.

In Latin America, Greater China and Asia/Pacific, the Aero 1500 is covered by a One-Year Limited Carry-In Warranty to Compaq or an Authorized Service Provider. The warranty covers parts and labor only.

Since Warranty delivery differs based on geographic region, contact the local Compaq Customer Support organization for information on coverage specific to a particular region.

Configuration Code/Model	Description	Spare Part
CXD1/1520	Worldwide, Mono	146649-001*
CXD1/1530	US Commercial, Mono	146649-001*
FBG5/1550	Pocket PC, English	177668-001**
FBG5/1550	Pocket PC, German	177668-041**
FBG5/1550	Pocket PC, French	177668-051**
FBG5/1550	Pocket PC, Italian	177668-061**
FBG5/1550	Pocket PC, Spanish	177668-071**

*The spare unit does not contain the following items: RAM/ROM module, main battery, or Stylus.

**The spare unit does not contain the main battery or the Stylus.

System RAM/ROM Module	Assembly	Spare Part
16 MB RAM/ROM, CE 2.11 – English	135368-001	146650-001
16 MB RAM/ROM (w/ Windows for Pocket PC) – English		177669-001
16 MB RAM/ROM, CE 2.11 – French	135368-051	146650-051
16 MB RAM/ROM (w/ Windows for Pocket PC) – French		177669-051
16 MB RAM/ROM, CE 2.11 – German	135368-041	146650-041
16 MB RAM/ROM (w/ Windows for Pocket PC) – German		177669-041
16 MB RAM/ROM, CE 2.11 – Italian	135368-061	146650-061
16 MB RAM/ROM (w/ Windows for Pocket PC) – Italian		177669-061
16 MB RAM/ROM, CE 2.11 – Spanish	135368-161	146650-071
16 MB RAM/ROM (w/ Windows for Pocket PC) – Spanish		177669-071

Miscellaneous	Assembly	Spare Part
AC Adapter, AU	118105-011	103710-011
AC Adapter, Euro	118105-021	103710-021
AC Adapter, U.K.	118105-031	103710-031
AC Adapter, U.S.	118105-001	103710-001
Auto Adapter	104934-001	109966-001
Battery Pack, Li-Ion	136283-001	146656-001

Continued

Aero 1500 Palm-Size PC

Miscellaneous	Assembly	Spare Part
Battery, Backup, Lithium 3V		234556-001
CD, ActiveSYnc 3.1 w/ Outlook 2000, English		177670-001
CD, ActiveSYnc 3.1 w/ Outlook 2000, French		177670-051
CD, ActiveSYnc 3.1 w/ Outlook 2000, German		177670-041
CD, ActiveSYnc 3.1 w/ Outlook 2000, Italian		177670-061
CD, ActiveSYnc 3.1 w/ Outlook 2000, Spanish		146660-071
CD Reference Guide and Software (multi-language)		177671-002
Case, Executive Portfolio		146654-001
Case, Slip	157051-002	146652-001
Cradle, Standard	136184-001	146651-001
Memory Card, 32-MB		176324-001
Memory Card, 64-MB		176325-001
Miscellaneous Plastics		146657-001
Modem , 4-position Cable		165224-001
Modem Adapter, AU		328558-011
Modem Adapter, Bel		328558-382
Modem Adapter, Den		328558-081
Modem Adapter, Fin		328558-351
Modem Adapter, FR		328558-051
Modem Adapter, GR		328558-041
Modem Adapter, IT		328558-061
Modem Adapter, The Netherlands		328558-331
Modem Adapter, Nor		328558-091
Modem Adapter, SP		328558-071
Modem Adapter, SE		328558-101
Modem Adapter, SW		328558-111
Modem Adapter, UK		328558-031
Modem Card, CF, 56K (US/Canada)		122717-001
Modem Card, CF, 56K (International)		122717-002
Serial Cable		148920-001
Serial Sync Cable	103286-001	103713-001

Aero 1500 Palm-Size PC

Memory Upgrade Chart

At the current time, there are no RAM upgrades for the Aero 1500 Palm-Size PC.

ADDITIONAL 20 MB COMPACTFLASH CARD- OPTION PN 104703-001
ADDITIONAL 32 MB COMPACTFLASH CARD- OPTION PN 104703-004
ADDITIONAL 40 MB COMPACTFLASH CARD- OPTION PN 104703-002
ADDITIONAL 64 MB COMPACTFLASH CARD- OPTION PN 104703-003

Note: RAM and ROM are mounted on the same module. Upgrading the ROM requires replacement of the existing module.